Importance Notice

 In table AB-6, Part D- Construction works, Sr. No-2 "Supply & laying lateral/branch/main trunk sewer including house connections by trenchless method" is wrongly linked with "Table AB-7, E10" instead of "Table AB-7 E11".

So, during financial evaluation we will put the value of "Table AB-7, E11" at the place of Table AB-6, Part-D, Sr. No-2 and accordingly final quoted price of bidder shall be completed.

2. There is no formula to add the 4 IPS at "Table AB-6,C 22" that's why the value of IPS not shown in "Table AB5, Sr. No-2, C-6".

So, during financial evaluation we will add manually the value of all 4 IPS shown in Table AB6 i.e, (C18+C19+C20+C21) & put the value in "Table AB5 sr. no-2" and accordingly final quoted price of bidder shall be completed.

3. There is no formula in "Table AB9" Sr. no-17 for getting amount.

So, during financial evaluation we will add the value of this item by performing calculation of QtyxRate quoted by bidder" in final amount and accordingly final quoted price of bidder shall be completed.

118°07118

Q 45,9